

General Meeting
August 8, 2018 at 7:00 pm
BTC Clubhouse

(abridged)

## Bubble background info

- It was bought used about 20 years ago so we are not sure how old it is
- How long is normal life of a bubble?
  - Warranty is 20-25 yrs but with care can extend beyond that
  - We will do a fabric test to know remaining life

#### Replacement Estimate

Basic Bubble \$372,000

• Options \$296,000

• Grade Beam \$ 99,000

Other \$ 40,000

\$807,000

# Replacement Quote Details (Farley Group, July 2018)

Basic Air Structure Package	. 32 oz. coated polyester Opaqe outer fabric 15 oz. vinyl coated liner fabric (similar to current liner) . 48 – 560 watt hanging <b>LED</b> lights wired from fixture to go walkway curtain along back on one side 300' X 15' . Freight to job site included On site supervision of installation of Air Structure PST & GST included; 20 yr warranty		\$372,000
Optional	. 3 Leaf revolving door (Entrance)	\$18,722	
· •	. Handicapped accessible personnel airlock . 40" Balanced Exit doors 4 X \$6,408	\$19,814 \$25,632	¢206.000
Package	. 51" balanced Exit door (for Lift Access)	\$6,934	\$296,000
Items	. 8X8X20' vehicle airlock entrance	\$30,775 ?	
iteilis	. 1.75 BTU Furnace (uninsulated) air structure	\$78,37 <mark>2</mark>	
	18,000 CFM Fan standby fan with Natural Gas Engine	\$29,967	
	. Tedlar Material (20 year Warranty)	\$72,163 X	
Grade	900 Linear Feet = \$494,000 or \$549.33 per linear foot Repair Replace 150 linear ft = \$659.70 per linear foot		\$ 99,000
Beam	Repair Replace 130 liliear It = 3033.70 per liliear 100t		. ,
	_  ¬ITEMS THAT ARE BTC'S RESPONSIBILITY:		
Other	Architect's fees, engineering, permits, mechanical, electrical drawings and stamps required •		4
Costs	Building code and by permit applications to be filed. Electrical and gas service hook and trades people required. Any temporary labour required and rental equipment needed for installation of		\$ 40,000
	equipment. All electrical line voltage control and computer wiring if required.		

High-side estimate: \$807,000

### **Bubble Savings Update**

- Restricted Bubble Savings Balance
- As of August, 2018:

\$490,000

### **Bubble Savings Gap**

